

Surface Preparation

INTRODUCTION

- 1. It is always important to clean surfaces just prior to any installation.
- 2. "Which preparation for which surface?" While many will work, a good rule of thumb for the last cleaning is:

SIGN MATERIAL	CLEANER
PAINTED METAL AND WOOD	Isopropyl Alcohol (IPA)
GLASS	IPA or Vinegar/Water Mix
ACRYLIC AND POLYCARBONATE	Non-siliconized Acrylic Cleaner or anti-static rag to remove static charge and last minute dust
BANNERS AND AWNINGS	IPA or Vinegar/Water Mix
FOR EXPANDED PVC SHEET	Vinegar followed by a quick wipe with Toluene
VEHICLE*	IPA / H20 (50:50) Mixture
PAINTED WALLS [†]	IPA / H20 (50:50) Mixture

CAUTIONARY NOTE:

While it may seem logical that a strong solvent will be the best cleaner for surfaces that are hard to stick film to - in the case of many plastics and paints this is wrong and can lead to premature sign failing due to embrittlement, cracking or loss of gloss. Use the mildest solvents possible and only clean until the surface dirt is gone.

* If the vehicle is new or has been waxed recently, Dupont wax remover is recommended to remove wax residue prior to cleaning with IPA water mixture. † Latex paint is more sensitive to IPA water mixture. Avoid prolonged exposure of cleaner to wall during surface preparation.

April 2014

USA:

200 Boysenberry Lane, Placentia, CA 92870, USA Dr Lelykade 22B, 2583CM Den Haag, The Netherlands 0 800 232 7161/+1 714 9 n +31 70 354 4311 800 329 2756 +31 70 355 7721